## **Elabscience**®

## Recombinant Human ALK-1 Protein(Fc Tag)

## Catalog Number: PDMH100306

Note: Centrifuge before opening to ensure complete recovery of vial contents.

Description			
Species	Human		
Source	Mammalian-derived Human ALK-1 proteins Asp22-Gln118, with an C-terminal Fc		
Calculated MW	35.5 kDa		
Observed MW	50 kDa		
Accession	P37023		
Bio-activity	Not validated for activity		
Properties			
Purity	> 90% as determined by reducing SDS-PAGE.		
Endotoxin	< 1.0 EU/mg of the protein as determined by the LAL method		
Storage	Generally, lyophilized proteins are stable for up to 12 months when stored at -20 to -80 °C. Reconstituted protein solution can be stored at 4-8°C for 2-7 days. Aliquots of		
	reconstituted samples are stable at $< -20^{\circ}C$ for 3 months.		
Shipping	This product is provided as lyophilized powder which is shipped with ice packs.		
Formulation	Lyophilized from a 0.2 $\mu$ m filtered solution in PBS with 5% Trehalose and 5%		
	Mannitol.		
Reconstitution	It is recommended that sterile water be added to the vial to prepare a stock solution of		
	0.5 mg/mL. Concentration is measured by UV-Vis.		

Data

kDa	М	R
80 60	_	
40	-	-
30		
20		
12		

SDS-PAGE analysis of Human ALK-1 proteins ,  $2\mu g/lane$  of

Recombinant Human ALK-1 proteins was resolved with

SDS-PAGE under reducing conditions , showing bands at  $50\,$ 

KD

## Background

Activin A receptor, type II-like 1 (ACVRL1), also known as ALK-1 (activin receptor-like kinase 1), is an endothelialspecific type I receptor of the TGF-beta (transforming growth factor beta) receptor family of ligands. On ligand binding, a heteromeric receptor complex forms consisting of two type II and two type I transmembrane serine/threonine kinases. ACVRL1 protein is expressed in certain blood vessels of kidney, spleen, heart and intestine, serving as an important role during vascular development. Mutations in ACVRL1 gene are associated with hemorrhagic telangiectasia type 2, also known as Rendu-Osler-Weber syndrome 2 and vascular disease.

For Research Use Only

Tel:400-999-2100